

VCDS
Windows Based VAG/VAS Emulator
VCDS Version: Beta 11.2.0 Data version: 20110305
www.Ross-Tech.com

Dealer/Shop Name:
Workshop Code: 000 00000

Self-Diagnosis Log
Monday, 08, July, 2013, 22:23:13:10074

VIN: WAUZZZ4E05N000420 License Plate:
Mileage: 179920km-111797mi Repair Order:

Chassis Type: 4E0

Scan: 01 02 03 05 06 07 08 09 15 16 17 18 19 1E 25 34 36 37 38 42
46 47 4F 52 53 55 56 61 62 65 69 72 76 77

VIN: WAUZZZ4E05N000420 Mileage: 179920km/111797miles

00-Steering Angle Sensor -- Status: OK 0000
01-Engine -- Status: Malfunction 0010
02-Auto Trans -- Status: OK 0000
03-ABS Brakes -- Status: Malfunction 0010
05-Acc/Start Auth. -- Status: OK 0000
06-Seat Mem. Pass -- Status: OK 0000
07-Control Head -- Status: OK 0000
08-Auto HVAC -- Status: OK 0000
09-Cent. Elect. -- Status: OK 0000
15-Airbags -- Status: OK 0000
16-Steering wheel -- Status: OK 0000
17-Instruments -- Status: OK 0000
18-Aux. Heat -- Status: Malfunction 0010
19-CAN Gateway -- Status: Malfunction 0010
1E-Media Player 2 -- Status: OK 0000
25-Immobilizer -- Status: OK 0000
34-Level Control -- Status: OK 0000
36-Seat Mem. Drvr -- Status: OK 0000
37-Navigation -- Status: OK 0000
38-Roof Electronics -- Status: OK 0000
42-Door Elect, Driver -- Status: OK 0000
46-Central Conv. -- Status: Malfunction 0010
47-Sound System -- Status: Cannot be reached 1100
4F-Centr. Electr. II -- Status: OK 0000
52-Door Elect, Pass. -- Status: Malfunction 0010
53-Parking Brake -- Status: OK 0000
55-Xenon Range -- Status: OK 0000
56-Radio -- Status: OK 0000
61-Battery Regul. -- Status: OK 0000
62-Door, Rear Left -- Status: OK 0000
65-Tire Pressure -- Status: Malfunction 0010
69-Trailer -- Status: OK 0000
72-Door, Rear Right -- Status: OK 0000
76-Park Assist -- Status: OK 0000
77-Telephone -- Status: OK 0000

VCDS
Self-Diagnosis Log
Monday, 08, July, 2013, 22:23:13:10074
Page 2

VIN: WAUZZZ4E05N000420 License Plate:

Address 01: Engine Labels: Redir Fail!
Part No SW: 4E0 910 401 J HW: 4E0 907 401 B
Component: 3.0L V6TDI G000AG 0020
Revision: --H01--- Serial number: AUX3Z0D4140932
Coding: 0011773
Shop #: WSC 38792 123 08560
VCID: 224FEEBB860F

5 Faults Found:

19591 - Intake Manifold Runner Control: Lower Stop not Reached

P3135 - 001 - Upper Limit Exceeded - Intermittent

Freeze Frame:

RPM: 0 /min
Torque: 167.7 Nm
Speed: 0.0 km/h
Voltage: 11.55 V
Duty Cycle: 88.8 %
Duty Cycle: 20.5 %
Duty Cycle: 20.5 %
Temperature: 31.5°C

17979 - Left Engine Mount Solenoid Valve (N144): Short to Plus

P1571 - 001 - Upper Limit Exceeded

Freeze Frame:

RPM: 0 /min
Torque: 167.7 Nm
Speed: 0.0 km/h
Voltage: 11.55 V
Bin. Bits: 1
Bin. Bits: 1
Bin. Bits: 1
Temperature: 31.5°C

17060 - Cylinder 6 Glow Plug Circuit (Q15): Electrical Fault

P0676 - 001 - Upper Limit Exceeded

Freeze Frame:

RPM: 819 /min
Torque: 105.3 Nm
Speed: 0.0 km/h
Duty Cycle: 1.0 %
Voltage: 11.93 V
Duty Cycle: 22.9 %
Temperature: 32.4°C
Bin. Bits: 10110000

17985 - Right Engine Mount Solenoid Valve (N145): Open Circuit

P1577 - 001 - Upper Limit Exceeded

Freeze Frame:

RPM: 840 /min
Torque: 89.7 Nm
Speed: 0.0 km/h
Voltage: 10.87 V

VCDS
Self-Diagnosis Log
Monday, 08, July, 2013, 22:23:13:10074
Page 3

VIN: WAUZZZ4E05N000420 License Plate:

Bin. Bits: 0
Bin. Bits: 0
Bin. Bits: 0
Temperature: 32.4°C

18277 - Transmission Mount Valve 1 (N262): Short to Ground

P1869 - 001 - Upper Limit Exceeded

Freeze Frame:

RPM: 840 /min
Torque: 89.7 Nm
Speed: 0.0 km/h
Duty Cycle: 1.0 %
Voltage: 10.87 V
Bin. Bits: 00101100
Torque: 288.6 Nm
Temperature: 32.4°C

Readiness: 0 0 1 1 1

Address 02: Auto Trans Labels: 09L-927-760.lbl
Part No SW: 4E0 910 156 F HW: 09L 927 156
Component: AG6 09L 3.0lTDI RdW 0060
Revision: 00000001 Serial number: 0021651
Coding: 0000001
Shop #: WSC 02313 785 00200
VCID: 2545F5A79721

No fault code found.

Address 03: ABS Brakes Labels: 4E0-910-517.lbl
Part No SW: 4E0 910 517 B HW: 4E0 614 517 BC
Component: ESP 5.7 allrad H44 0510
Coding: 0008357
Shop #: WSC 00001 000 00000
VCID: 224FEEBB860F

1 Fault Found:

00003 - Control Module
014 - Defective

VCDS
Self-Diagnosis Log
Monday, 08, July, 2013, 22:23:13:10074
Page 4

VIN: WAUZZZ4E05N000420 License Plate:

Address 05: Acc/Start Auth. Labels: 4E0-910-131.lbl
Part No SW: 4E0 910 131 HW: 4E0 909 131
Component: FBS AUDID3 H03 0140
Revision: 01403903 Serial number: AUX3Z0D4140932
Coding: 0263168
Shop #: WSC 02311 785 00200
VCID: D8BB0C5310D3

Part No: XXXXXXXXXXXX
Component: ELV XXXX

No fault code found.

Address 06: Seat Mem. Pass Labels: None
Part No SW: 4E0 910 760 C HW: 4E0 959 760
Component: Sitzmemory BFS H08 0060
Revision: 00000000 Serial number: 5DS 008 795-03
Coding: 4063328
Shop #: WSC 00000 785 00200
VCID: 2341EBBF9915

No fault code found.

Address 07: Control Head Labels: 4E0-910-7xx-07.lbl
Part No SW: 4E0 910 769 F HW: 4E0 035 729
Component: Interfacebox H43 5540
Revision: 00000000 Serial number: 343DV047535975
Coding: 0000012
Shop #: WSC 00481 935 84751
VCID: 2F69178FC5DD

Part No: 4E0 910 609 A
Component: Bedienteil MMI H42 0020

No fault code found.

Address 08: Auto HVAC Labels: None
Part No SW: 4E0 910 043 A HW: 4E0 820 043 A
Component: KLIMAAUTOMAT 016 0300
Revision: 00000025 Serial number: 00000000043890
Coding: 0264321
Shop #: WSC 02311 785 00200
VCID: 1B31D35FA165

No fault code found.

VCDS
Self-Diagnosis Log
Monday, 08, July, 2013, 22:23:13:10074
Page 5

VIN: WAUZZZ4E05N000420 License Plate:

Address 09: Cent. Elect. Labels: 4E0-910-279.lbl
Part No SW: 4E0 910 279 J HW: 4E1 955 113 B
Component: ILM Fahrer H12 0190
Coding: 0123122
Shop #: WSC 02313 785 00200
VCID: 2F69178FC5DD

Subsystem 1 - Part No: 4E1 910 113 B
Component: Wischer WWS D3 H50 0400
Coding: 00000037
Shop #: WSC 02313

Subsystem 2 - Part No: 4E0 910 557
Component: REGENLICHTSENSORH10 0040
Coding: 00139548
Shop #: WSC 02313

No fault code found.

Address 15: Airbags Labels: 4E0-910-655-84.lbl
Part No SW: 4E0 910 655 HW: 4E0 959 655 G
Component: Airbag 8.4E+ H10 0940
Coding: 0430707
Shop #: WSC 02313 785 00200
VCID: E3C12BBF5995

No fault code found.

Address 16: Steering wheel Labels: 4E0-910-549.lbl
Part No SW: 4E0 910 549 HW: 4E0 953 549
Component: Lenksdulenmodul H13 0040
Coding: 0012141
Shop #: WSC 02311 785 00200
VCID: E5C535A757A1

Part No: XXXXXXXXXXXX
Component: Lenkradmodul H04 0080

No fault code found.

VCDS
Self-Diagnosis Log
Monday, 08, July, 2013, 22:23:13:10074
Page 6

VIN: WAUZZZ4E05N000420 License Plate:

Address 17: Instruments Labels: 4E0-910-xxx-17.lbl
Part No SW: 4E0 910 900 K HW: 4E0 920 900 K
Component: KOMBIINSTR. VDO H47 0200
Revision: D01 Serial number: AUDID3D4000179
Coding: 0016028
Shop #: WSC 00481 935 84751
VCID: 2759FFAFED2D

No fault code found.