

ALI & SONS COLLC

Motors Division

Tel. No. 02-5553363 / Fax No. 02-5555657

Estimation Sheet

①

Customer Name: MR. GHAZI	Date: 30-07-2007
VIN Number: WVAJN944E34N006015	Km: 133274
Registration Number: 76374 AD	Model: A8
Job Card Number: 2009104322	P.O.F Number:

Laker 5/Part

1	Head light switch (Peeling)	200	640
2	Arm Rest cover (lock defect) 2pc	350	3040
3	Front Right Door lock unlock switch Peeling off	200	356
4	Front left window switch peeling	200	131
5	Rear Right window switch (Peeling)	200	131
6	Rear Right Door lock unlock switch	200	356
7	Rear Boot lid motor (not lift up)	250	3255
8	Front center console A/c on/off switch (Peeling off) w/set	250	8070
9	Front sunRoof defect n motor noisy	375	995
10	UPPER ARM Bush broken	600	516
11	Front UPPER Engine mounting is broken	375	691

Technician Name: *[Signature]*Foreman Name: *[Signature]*

Service Advisor Signature:

Segment

Disc:

Total:

Grand Total:

Date:

Time:

Signature:

Customer Approval

Labour Amt.

Parts Amt.

Note: This Estimation is only valid for 30 days

parts statement part IVA (not available) bill on order (state order number and ETA)

Difenture oil